

Scr 26 9 41 AN 199

ENVIRONMENTAL COMPLIANCE SERVICES, INC. TANASCENCE.

October 25,1999 Project #40191 Document: Site inv

Mr. Chuck Schwer, Supervisor Sites Management Section VT DEC Waste Management Division 103 South Main Street Waterbury, VT 05671-0404

RE:

Site Investigation Report

Brattleboro D.P.W. Well Field, Route 30, Brattleboro, VT

DEC Site #99-2661

Dear Mr. Schwer:

Enclosed please find the above-referenced report for your review. If you have any questions or require further information, please call me at 802-257-1195.

Sincerely,

ENVIRONMENTAL COMPLIANCE SERVICES, INC.

David C. Balk, P.G.

Project Manager

enclosure

cc: Steve Barrett, Brattleboro DPW

David C. Ball

Ser
6
ധ
Ļ.
Fig.

Phase	Туре
X Initial Site Investigation ☐ Corrective Action Feasibility Investigation ☐ Corrective Action Plan ☐ Corrective Action Summary Report ☐ Operations and Monitoring Report	☐ Work Scope X Technical Report ☐ PCF Reimbursement Request ☐ General Correspondence

Site Investigation Report

Brattleboro Well Field Water Treatment Building
Route 30
Brattleboro, Vermont
SMS Site #99-2661

Prepared for:

Brattleboro Department of Public Works Brattleboro, Vermont 05301 Contact: Steve Barrett Phone: (802) 254-4255

Prepared by:

Environmental Compliance Services, Inc. 157 Old Guilford Road #6 Brattleboro, VT 05301 Contact: David C. Balk, P.G. Phone: (802) 257-1195

Project No.: 40191.10

October 14, 1999

Site Investigation Report Brattleboro Well Field Water Treatment Building Site #99-2661

TABLE OF CONTENTS

1.0 Introduction
2.0 Site Description
3.0 Work Performed
3.1 Soil Borings and Monitoring Wells
3.2 Field Screening of Soil Samples
3.3 Groundwater Sampling
4.0 Results
4.1 Groundwater Flow Direction
4.2 Laboratory Analysis of Groundwater Samples
5.0 Risk Evaluation
5.1 Potential Sources
5.2 Potential Receptors
6.0 Conclusions and Recommendations
6.1 Conclusions
6.2 Recommendations
Appendices
Appendix A Site Locus Map
Appendix B Site Plan
Appendix C Soil Boring/Monitoring Well Construction Logs
Appendix D. Laboratory Data Sheets and Chain of Custody Record

1.0 Introduction

On July 20, 1999 a 1,500 gallon #2 fuel oil underground storage tank (UST) was removed from outside the Brattleboro Well Field Water Treatment Building ("the site;" see locus map, Appendix A). Environmental Compliance Services, Inc. (ECS) screened soils from the tank excavation with a Photovac Model 2020 photoionization detector (PID) for the presence of Volatile Organic Compound (VOC) concentrations. The levels of contamination ranged from 0 to 178 parts per million (ppm). Approximately 15 cubic yards of contaminated soil was removed and stockpiled at the Department of Public Works Facility on Fairground Road. A soil sample was collected on July 22, 1999 from the tank grave and submitted for analysis of VOCs and Total Petroleum Hydrocarbons. No concentrations were detected above the minimum detection limit for the compounds analyzed. A tank closure report was submitted to the VT DEC.

Due to the sensitive nature of the site, subsurface investigations to assess the extent and degree of petroleum contamination in soil and/or groundwater at the site was conducted.

This report documents the work performed by ECS at the site and presents results, conclusions and recommendations.

2.0 Site Description

The subject property exists at an elevation of approximately 238 feet above mean sea level. The Brattleboro Well Field property consists of one building and a series of underground water storage tanks. The site is surrounded by wetlands. To the west is Route 30 and to the east is the West River. To the south is the Retreat Meadows and Brattleboro Retreat Hospital, a rehabilitation facility. The site is maintained as a backup source for water in the event of a catastrophic failure of the town water supply.

Observations made during the removal of the fuel oil UST in July 1999 indicate that the soils in the tank pit were dark brown coarse sand and gravel to 12 1/2 feet below ground surface (bgs). Groundwater oxidation staining was encountered at approximately seven feet bgs with standing water at 12 ½ feet bgs. No ledge was encountered in the tank grave. A new propane UST was installed approximately 30 feet south of the former UST location.

3.0 Work Performed

3.1 Soil Borings and Monitoring Wells

During the UST removal on July 20, 1999 a monitoring well (ECS-1) was installed in the tank grave via a town operated backhoe. ECS installed three soil borings on September 9, 1999, designated SB-1, SB-2, and SB-3 using a truck mounted hydraulic push probe drill rig (Earthprobe). Monitoring well and soil boring locations are shown on the site plan in Appendix B. Monitoring well ECS-1 is 13 feet deep, and constructed of 2 inch diameter schedule 40 PVC slotted screen (size 10). Soil boring logs are presented in Appendix C.

3.2 Field Screening of Soil Samples

During Earthprobe soil borings, continuous soil samples were obtained at four-foot intervals from each of the boreholes. The samples were field screened for VOCs with a PID (field calibrated to an isobutylene span gas and referenced to benzene), using bag headspace protocol. No VOC levels were detected above the minimum detection limit of 0.1 ppmv in the borings.

3.3 Groundwater Sampling

Groundwater from monitoring well ECS-1 was sampled on July 29, 1999, using a disposable plastic bailer. The sample was obtained after three borehole volumes of groundwater were evacuated from the monitoring well. During the advancement of Earthprobe soil borings on September 9,1999, groundwater was collected from the borings using plastic tubing equipped with a check valve. A duplicate groundwater sample from SB-3 was obtained for quality control purposes. All samples were stored on ice immediately upon collection, and refrigerated until delivery was made to Spectrum Analytical, Inc. in Agawam, Massachusetts for analysis of BTEX compounds, MTBE, Trimethylbenzenes and Naphthalene by EPA Method 8021B and Total Petroleum Hydrocarbons (TPH) by EPA Method 8100M.

4.0 Results

4.1 Groundwater Flow Direction

Groundwater at the site could be interpreted as easterly in the direction of the West River. The site locus map shows the general topography in the area and the close proximately of the West River. Based on past investigations of sites in the Brattleboro area flood plain, the groundwater table is considered relatively flat at the site, trending slightly to the east.

4.2 Laboratory Analysis of Groundwater Samples

The groundwater samples obtained on July 29, and September 9, 1999 were analyzed by EPA Methods 8021B and 8100M. Results are presented in Table 2, which includes Primary Groundwater Quality Standards (PGQS) for reference. The complete laboratory data sheets and chain of custody record are presented in Appendix D.

Table 2. Resu	lts of laborator	v analysis of	groundwater samp	les.
---------------	------------------	---------------	------------------	------

Date	Compound	PGQS	ECS-1	SB-1	SB-2	SE	3-3
9/9/99	Benzene	5.0	NT	ND	ND	ND	ND
	Toluene	1000	NΤ	ND	ND	ND	ND
	Ethylbenzene	7000	NT	ND	ND	ND	ND
	Xylenes	10,000	NT	ND	ND	ND	ND
	Total BTEX		NT	ND	ND	ND	ND
	Napthalene	20	NT	ND	ND	ND	ND
	1,2,4-Trimethylbenzene	5.0	NT	ND	ND	ND	ND
	1,3,5-Trimethylbenzene	4.0	NT	ND	ND	ND	ND
	MTBE	40	NT	ND	ND	ND	ND
	TPH		NT	ND	ND	ND	ND
7/29/99	Benzene	5.0	ND	NA	NA		ŇΑ
	Toluene	1000	ND	NA	NA		NA
	Ethylbenzene	7000	ND	NA	NA		NA
	Xylenes	10,000	ND	NA	NA		NA
	Total BTEX	····	NĎ	NA	NA	•	NA
	Naphthalene	20	ND	NA	NA		NA
	1,2,4-Trimethylbenzene	5.0	ND	NA	NA		NA
	1,3,5-Trimethylbenzene	4.0	ND	NA	NA		NA
	MTBE	40	ND	NA	NA		NA
	TPH		11	NA	NA		NA

Results reported in mg/L (ppb).

ND = Not detected.

Split cells indicate duplicate analyses.

Boldface type indicates PGQS exceedances.

NA = Not applicable no boring installed.

NT = Not tested for.

5.0 Risk Evaluation

5.1 Potential Sources

Only low levels of TPH were detected in a groundwater sample from the monitoring well located in the tank grave. It is reasonably clear that the source of this contamination is related to the fuel oil UST which has been removed from the site. Approximately 15 cubic yards of soil were excavated and polyencapsulated at the Department of Public Works Yard located on Fairground Road. This additional source of contamination was stockpiled off-site due to the sensitive nature of the well field.

5.2 Potential Receptors

The potential sensitive receptors of most immediate concern are site workers. The Brattleboro Well Field Water Treatment Building is located approximately 3 feet topographically and hydrogeologically downgradient from the tank grave. The municipal water supply well is located downgradient 120 feet from the tank grave. There are no other water supplies known to be located within a ½ mile radius of the site. The only downgradient structure is the Well Field Treatment building, located between the tank grave and the West River. Air in the building was screened for VOCs with a PID. No VOCs were detected in the building above 0.1 ppmv.

The West River, located approximately 300 feet downgradient and to the east, is the nearest potential sensitive environmental receptor.

6.0 Conclusions and Recommendations

6.1 Conclusions

ECS presents the following conclusions based on the information obtained at the site to date:

- Groundwater flow direction at the site can be interpreted to be to the east, in the same direction
 as the West River.
- Low levels of contaminants tested for were detected in groundwater from the monitoring well
 installed in the tank grave of the fuel oil UST removed from the site in July 1999. No PGQS
 levels were exceeded in groundwater from the monitoring well or soil borings.
- Soil boring and associated groundwater samples did not detect any concentrations of VOCs or TPH above the minimum detection limits.
- No bedrock is located in the tank grave, groundwater is within 7 feet bgs, and no confining layer was present.
- No VOCs were detected in the indoor air of the site building, the nearest downgradient structure from the tank grave.
- The probable source of the release, a 1,500 gallon fuel oil UST, has been removed from the site. Presently, contamination of soil and groundwater appears to have been restricted to the tank grave.
- The water supply wells are presently tested on a quarterly basis for VOCs via EPA Method 524.5 drinking water standards under the direction of Tim Raymond at the VT DEC.

6.2 Recommendations

ECS recommends that the monitoring well at this site be sampled again in the spring time, when groundwater elevations are highest. Results from the quarterly water supply well sampling should be obtained by the Sites Management Section of the VT DEC for inclusion in the UST release file.

ECS recommends that samples from the polyencapsulated soil stockpile be screened for VOCs with a PID, in the summer of 2000 to assess contaminant levels in the pile and determine whether they may be thin spread on site.

Pending the results of the next sampling round the site maybe considered for a Sites Management Activities Completion designation (SMAC).

Ceran

\40191.10\Site_inv

Appendix A

Site Locus Map




Scale: 1 inch equals 2000 feet

Route 30

Brattleboro, VT 05301

Appendix B

Site Plan



Site Sketch		Brattleboro Town Well Fields
	Not to Scale	Route 30
]	Brattleboro, Vermont

Appendix C

Soil Boring Logs

						•		BORING NO.:		SB-1		
		Environ	mental Complia	nce Services, Inc.	SOIL BOR	ING and MONITOR	ING WELL	DOCUMENT NO.:				
						NSTALLATION LO		SHEET	1	OF	1	
7		157 Old (Guilford Rd. #6,Braitle	poro, Vermora USSUI	."	· · · · · · · · ·		3/1661	LOCATION		<u>'</u>	
BORING	COMPAN	Environmental	I Compliance Se	rvices, Inc.	JOB NUMBER:	40191.00		50-1	SB-1 6 1 1111		A •	
SORING COMPAI ADDRES	NY	Y 588 Silver Street Anawam Massachusetts		PROJECT NAME:	Brattleboro DPW		30 \		Bricain			
FOREAU	AN:	Dominique Ca	ırdinale		PROJECT ADDRESS:	Rte 30 Brattleboro	,VT]	- 11			
ECS INS	PECTOR:	L. Gilmore			CLIENT NAME:	Steve Barrett	<u> </u>					
	GROUN	DWATER OBSER	VATIONS		CASING	SAMPLER	CORE BARREL		DEWARY			
	Date	Depth	Stabilization Time	TYPE		Macro		Casing Elevation (ft.)				
		<u> </u>		INSIDE DIAMETER		1.5		PVC Elevation (fL)				
				HAMMER WEIGHT		Direct Drive		Surface Elevation (ft.) Date Started	 	9/9/99		
				HAMMER FALL	Sampled using Earth	Proba	<u> </u>	Date Completed	 	9/9/99		
				NOTES:	Camples Gaing Cardi	1	 -	Date Competed		1	T	
Depth	Sample Number	Sample Depths	Penetration/ Recovery	Blows per 6" penetration	Strata Changes		Soil Descriptions		Well As Built	Field Testing ⁽¹⁾	Notes	
٥		0-4	474		f. SAND and SILT	Brown fine SAND and SILT, trace Cobbles		bbles		BOL		
]		-				<u> </u>	
									ŀ		ļ	
	<u> </u>						4 011 % 4 0	LLI		- 25	 	
4	ļ	4 - 8	4'/4'		ļ	Brown fine SAND	and SILT, trace Co	bbies		3.5		
											1	
	<u> </u>				ł				1			
١.	<u> </u>	2 42	4140 E1			Brown mf. SAND	T II2 bas (7.0		
8		8 - 12	4'/3.5'			DIOWIT III1. SPATE				7.0	 .	
	<u> </u>		•		m. ŞAND						1	
	<u> </u>				111. 92415	1					2	
12	 	12 - 16			End of Soring							
12	 	14-10	<u></u> .	 						·····		
											1	
					1				ļ		· · ·	
16		16 - 20	i		1							
		•]							
									1	<u></u>	<u> </u>	
						į	•				<u> </u>	
20		20 - 24		_							<u> </u>	
					}					ļ	 	
	<u> </u>		<u> </u>		1							
				<u> </u>	1					<u> </u>	 	
24		24 - 28			4	[ļ		-	
				· -	4					-	+	
		1	 	 	-	1					1	
		59 55	ļ		-{						 	
28	<u> </u>	28 - 32		 	{							
			1	1	1						 	
			 		1						 	
<u> </u>	<u></u>	1	<u></u>	l organic vapors (referenc		I de la contraction de la cont		analad adl anashir to	1	Managaria Managaria		

Photovac Model 2020 photolonization detector (PID). Results reported in parts per million by volume (ppmv). Detection limit calibrated to 0.2 ppmv.

^{2.} Water Table encountered at approximately 11' BGS.

				··· ·	Ι΄			BORIN	G NO.:	<u> </u>	\$8-3		
		Enviror	rmental Complia.	nce Services, Inc.	SOIL BOR	ING and MONITOR	ING WELL	0000	MENT NO.:	·			
			Guilford Rd. ,#8,8rattle			NSTALLATION LO		SHEET		1	OF	1	
			ł					LOCATION					
00000	COMPAN	Carrierannak	al Compliance Se	nicas Inc	JOB NUMBER:	40191.00		1	in			<u> </u>	
BORING	,		eet, Agawam, Ma		PROJECT NAME:	Brattleboro DPW		1	\cap 1	BUILDIN	a <u>.</u>	N.	
COMPA FOREM		Dominique Ca			PROJECT ADDRESS:	Rte 30 Brattleboro,	,VT	Sux	WILK C	-BAMP			
		L. Gilmore			CLIENT NAME:	Steve Barrett		~		1	9 883		
ECS INS		OWATER OBSER	ZANITAV	T T	CASING	SAMPLER	ÇORÉ BARREL	1 :		'	200	5 5	
├	Date	Depth	Stabilization Time	TYPE		Macro		Casing	Elevation (ft.)	1			
} 	,	Осран	Grand Trans	INSIDE DIAMETER		1,5		PVC E	levation (ft.)			•	
├			· · · · ·	HAMMER WEIGHT		Direct Drive		Surface	a Elevation (ft.)				
-			 -	HAMMER FALL				Date S	larted	 	9/9/99		
				NOTES:	Sampled using Earthf	robe	l	Date C	ampleted		9/9/99		
 -	Şample	Sample	Penetration/	<u> </u>		· · · · · · · · · · · · · · · · · · ·	Cait Canadaliana			114.01 4 - 5 - 76	Field		
Depth	Number	Depths	Recovery	Stows per 6" penetration	Strata Changes		Soit Descriptions			Well As Buill	Testing (1)	Notes	
0	S-1	0 - 4	4'/3.5'		m. SAND	brown mf, SAND,	, some Cobbles, tra	ace O.N	A.		5.1	ļ. <u></u>	
	<u></u>				f. SAND								
				<u> </u>]			_				ļ	
4	S-2	4 - 8	473.5		m,-f, \$AND	brown mf. SAND,	, some Cobbles an	d Silt			9.6	ļ	
ļ			·]								
					J								
]					1		<u> </u>	
8	S-3	8 - 12	473.5		m. SAND	Brown mf. SAND	and SILT				18.7		
					f. SAND and SILT								
					SILT					1		2	
]							3	
12		12 - 16			End of Boring	1				1			
İ]					1		<u> </u>	
			1									1	
			1		1]	
16		16 - 20			· ·]	
				•	1]	
		···-	 		1								
				·· -	1								
20		20 - 24	 	· · · ·	1								
					1	į						·	
		F			1								
i					1								
24		24 - 28	<u> </u>]					1			
			· · · · · ·]								
]							<u> </u>	
					1								
28		28 - 32	1		1								
l		 "	 		1								
					1							<u> </u>	
ĺ			1		1	1							

^{1.} Field testing values represent total volatile organic vapors (referenced to a benzene standard) measured in the headspace of sealed soil sample jars or Zip-lock TM bags, with a Photovac Model 2020 photoionization detector (PID). Results reported in parts per million by volume (ppmv). Detection limit calibrated to 0.2 ppmv.

^{2.} Areas of possible staining detected at 10' BGS


^{3.} Water Table encountered at approximately 10 BGS

							· 	BORING NO.:		SB-2	 1
K		Environ	mantal Complia	nce Services, Inc.	SOIL BORING and MONITORING WELL			DOCUMENT NO.:			
			Guilford Rd. ,#6,Brattlet			ISTALLATION LO		SHEET	1	ÓF	1
T							LOCATION		—		
2001110	COMPAN	Cauleanmonto	I Compliance Ser	nicae Inc	JOB NUMBER:	40191.00	·				
BORING			eet, Agawam, Ma			Brattleboro DPW		1		n	T_{i}
COMPAI FOREM		Dominique Ca			PROJECT ADDRESS:	Rte 30 Brattleboro,	Vτ	1	177	Bucon	9 ~
	PEÇTOR:	L. Gilmore			CLIENT NAME:	Steve Barrett		SIDEN	IALE -	-RANY	2
203 1113		DWATER OBSER	PROITAN		CASING	SAMPLER	CORE BARREL	1	056	<u>. 1</u>	
	Date	Depth	Stabilization Time	TYPE		Macro	•	Casing Elevation (ft.)	<u> </u>		
	7410	Depili	June Level 1414	INSIDE DIAMETER		1.5		PVC Elevation (ft.)	1	····	
		- 		HAMMER WEIGHT		Direct Drive		Surface Elevation (fl.)			
				HAMMER FALL				Date Started		9/9/99	
				NOTES:	Sampled using EarthF	rabe	L-	Date Completed		9/9/99	
S	Sample	Sample	Penetration/	Blows per 6° penetration	Strata Changes		Soil Descriptions	L	Well As Built	Field	Notes
Depth	Number	Depths	Recovery	Blows per of peneuration				0 14	THE AS DUIL	Testing (1)	110/62
0	S-1	0-4	4'/4'		Organic Matter	brown mf. SAND,	some Cobbles, tra	ce O.M.	'	5.1	
i '					m. SAND&COBBLE						
	ļ			<u> </u>	-						
				<u> </u>		- 4 SAND	samo Cobbles ass	1 Cit		0.6	
4	\$-2	4 - 8	4'/3.5'		mf. SAND	brown mf. SAND,	Stille Cooties and	3 SIII		9.6	
	<u> </u>			··	COAND and OUT	İ					
	<u> </u>				f. SAND and SILT						
_		2 42	4'/3.5'		Cobbles	Brown mf. SAND	and SILT			18,7	
8	\$-3	8 - 12	4/3.5		f. SAND and SILT	BIOWIT IIII. GAND	and OIL			10.1	2
ļ		<u> </u>	<u> </u>		SILT						3
İ	<u> </u>		ļ		f. SAND and SILT						
40		12 10	<u> </u>		End of Boring						<u> </u>
12		12 - 16	<u> </u>		End of Bonnig						
		-	<u> </u>		1						
		40.00		<u> </u>							
16		16 - 20		-	1						
					1						
1			1		1	1					
20		20 - 24			1				ŀ		
20		20-24			1					·	
l	}				†						
	 				1						
24	 	24 - 28			1	[
"	-	<u> </u>	 	1	1	1					
			 		1						
			· · · · ·		1 ,	1					
28	\vdash	28 - 32			1						
]		1	 	†	1						
	-	1	· ·		1						
			<u> </u>	1	1				1		l

^{1.} Field testing values represent total volatile organic vapors (referenced to a benzene standard) measured in the headspace of sealed soil sample jars or Zip-tock TM bags, with a Photovac Model 2020 photoionization detector (PID). Results reported in parts per million by volume (ppmv). Detection limit calibrated to 0.2 ppmv.

^{2.} Areas of possible staining detected at 9' BGS

^{3.} Water Table encountered at approximately 10 BGS



Laboratory Data Sheets and Chain of Custody Record



Massachusetts Certification M-MA 138
Connecticut Approval # PH 0777
Rhode Island # 98 & Maine # n/a
New Hampshire ID # 2538
New York ID #11393
Florida HRS87448

RECEIVED AUG - 9 1999

ECS, Inc. 157 Old Guilford Road, #6 Brattleboro, VT 05301 August 4, 1999

Attn: David Balk

Client Project No.: 40191

Location: Brattleboro DPW Wellfields-VT

Lab ID No.	Client ID	Analysis Requested
AB51541	ECS-1	EPA Method 8021B TPH by GC
AB51542	TRIP	EPA Method 8021B

Authorized by

Haniball Yayeh
President/Laboratory Director

Laboratory Report

Client ID: ECS-1 Lab ID No: AB51541 Location: Brattleboro DPW Wellfields-VT

Client Job No: 40191

Matrix: Ground Water Sampled on 07/29/99 Client ECS Received on 07/30/99 by KC QC and Data Review by MD

Preservative: Refrigeration, HCl Container: 2 VOA Vials Condition of Sample as Received: Satisfactory Delivered by: Client

Volatile Organics

Parameter for AB51541	Result (in ug/L)	MDL		
	, , ,		Analyzed	Analyst
Benzene	Not detected	1.0	08/03/99	SK
Toluene	Not detected	1.0	08/03/99	SK
Ethylbenzene	Not detected	1.0	08/03/99	SK _
m,p-Xylenes	Not detected	2.0	08/03/99	SK
o-Xylene	Not detected	1.0	08/03/99	SK
Naphthalene	Not detected	1.0	08/03/99	SK _
1,2,4-Trimethylbenzene	Not detected	1.0	08/03/99	SK
1,3,5-Trimethylbenzene	Not detected	1.0	08/03/99	SK
Methyl-t-butyl ether	Not detected	1.0	08/03/99	SK -
Bromofluorobenzene (%SR)	92		08/03/99	sk

Laboratory Report

Client ID: ECS-1 Lab ID No.: AB51541 Location: Brattleboro DPW Wellfields-VT

Client Job No.: 40191

Matrix: Ground Water Collected: 07/29/99 by ECS Received on 07/30/99 by KC QC and Data Review by MD

Preservative: Refrigeration Container: 1 Amber Glass

Condition of Sample as Received: Satisfactory Delivered by: Client

Total Hydrocarbons by GC

Modified EPA Method 8100

Parameter	Result (mg/L)	MDL	Extracted	Analyzed	Analyst
Total Hydrocarbons (GC)	11		08/02/99	08/03/99	LR
Fingerprint based quantification:					
Gasoline	Not detected	0.2	08/02/99	08/03/99	LR
Fuel Oil #2	Not detected	0.4	08/02/99	08/03/99	LR
Fuel Oil #4	Not detected	0.7	08/02/99	08/03/99	LR
Fuel Oil #6	Not detected	0.7	08/02/99	08/03/99	LR
Motor Oil	*	0.7	08/02/99	08/03/99	LR
Ligroin	Not detected	0.4	08/02/99	08/03/99	LR
U	Not detected	0.4	08/02/99	08/03/99	LR
	**	0.7	08/02/99	08/03/99	LR
Unidentified	11		08/02/99	08/03/99	LR
	Total Hydrocarbons (GC) Fingerprint based quantification: Gasoline Fuel Oil #2 Fuel Oil #4 Fuel Oil #6 Motor Oil Ligroin Aviation Fuel Other Oil	Total Hydrocarbons (GC) 11 Fingerprint based quantification: Gasoline Not detected Fuel Oil #2 Not detected Fuel Oil #4 Not detected Fuel Oil #6 Not detected Motor Oil * Ligroin Not detected Not detected Aviation Fuel Not detected Not detected Not detected Not detected Aviation Fuel Not detected Not detected Other Oil **	Total Hydrocarbons (GC) 11 Fingerprint based quantification: Gasoline Not detected 0.2 Fuel Oil #2 Not detected 0.4 Fuel Oil #4 Not detected 0.7 Fuel Oil #6 Not detected 0.7 Motor Oil * 0.7 Ligroin Not detected 0.4 Aviation Fuel Not detected 0.4 Other Oil ** 0.7	Farameter Extracted Total Hydrocarbons (GC) 11 08/02/99 Fingerprint based quantification: Gasoline Not detected 0.2 08/02/99 Fuel Oil #2 Not detected 0.4 08/02/99 Fuel Oil #4 Not detected 0.7 08/02/99 Fuel Oil #6 Not detected 0.7 08/02/99 Motor Oil * 0.7 08/02/99 Ligroin Not detected 0.4 08/02/99 Aviation Fuel Not detected 0.4 08/02/99 Other Oil ** 0.7 08/02/99	Extracted Analyzed O8/02/99 O8/03/99

Petroleum identification is determined by comparing the GC fingerprint obtained from the sample with a library of GC fingerprints obtained from petroleum products. Possible match categories are as follows;

Gasoline - includes regular, unleaded, premium, etc.

Fuel Oil #2 - includes home heating oil, #2 fuel oil and diesel.

Fuel Oil #4 - Includes #4 Fuel Oil.

Fuel Oil #6 - includes #6 oil and bunker "C" oil.

Motor Oil - includes virgin and waste automobile.

Ligroin - includes mineral spirits, petroleum naphtha, vm&p naphtha.

Aviation Fuels - includes Kerosene, Jet A and JP-4.

Other Oil - includes lubricating and cutting oil and silicon oil.

Factors such as microbial degradation, weathering and solubility generally prevent specific identification within a petroleum category. A finding of "unidentified" means that the sample fingerprint was characteristic of a petroleum product, but could not be matched to a fingerprint in the library.

After fingerprint identification, the amount present in the sample is quantified using a calibration curve prepared from a petroleum product of the same category as the identified petroleum. Unidentified petroleum is quantified using a petroleum calibration that approximates the distribution of compounds in the sample. A * in the results column indicates the petroleum calibration used to quantify unidentified samples.

Laboratory Report

Client ID: TRIP

Lab ID No: AB51542

Matrix: Deionized Water Sampled on07/29/99 Client ECS Received on 07/30/99 by KC QC and Data Review by MD

Location: Brattleboro DPW Wellfields-VT

Client Job No: 40191

Preservative: Refrigeration, HCl Container: 1 VOA Vial Condition of Sample as Received: Satisfactory Delivered by: Client

Volatile Organics

Parameter for AB51542	Result (in ug/L)	MDL		
			Analyzed	Analyst
Benzene	Not detected	1.0	08/03/99	SK -
Toluene	Not detected	1.0	08/03/99	SK
Ethylbenzene	Not detected	1.0	08/03/99	SK
m,p-Xylenes	Not detected	2.0	08/03/99	SK
o-Xylene	Not detected	1.0	08/03/99	SK
Naphthalene	Not detected	1.0	08/03/99	SK _
1,2,4-Trimethylbenzene	Not detected	1.0	08/03/99	SK
1,3,5-Trimethylbenzene	Not detected	1.0	08/03/99	SK
Methyl-t-butyl ether	Not detected	1.0	08/03/99	sk -
Bromofluorobenzene (%SR)	75		08/03/99	SK .

Spectrum Analytical, Inc. Laboratory Report Supplement

References

- Methods for the Determination of Organic Compounds in Drinking Water. EPA-600/4-88/039. EMSL 1988.
- Methods for Chemical Analysis of Water and Wastes. EPA 600/4-79-020. EMSL 1983.
- Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater. EPA 600/4-82-057. EMSL 1982.
- Test Methods for Evaluating Solid Waste. Physical/Chemical Methods. EPA SW-846. 1986.
 - Standard Methods for the Examination of Water and Wastes. APHA-AWWA-WPCF, 19th Edition, 1995.
 - Standard Methods for Comparison of Waterborne Petroleum Oils by Gas Chromatography. ASTM D 3328, 1982,
 - Oil Spill Identification System. U.S. Coast Guard CG-D-52-77. 1977.
 - Handbook for Analytical Quality Control in Water and Wastewater Laboratories. EPA 600/4-79-019. EMSL 1979.
- Choosing Cost-Effective QA/QC (Quality Assurance/Quality Control) Programs for Chemical Analyses. EPA 600/4-85/056. EMSL 1985.

Report Notations

Not Detected,	=	The compound was not detected at a	concentration equal to or above
Not Det, ND or nd		the established method detection limi	
NC	=	Not Calculated	
MCL	₽	EPA Maximum Contamination Level	
VOA	=	Volatile Organic Analysis	
BFB		4-Bromofluorobenzene	(An EPA 624 Surrogate)
p-DFB	==	1,4-Difluorobenzene	(An EPA 624 Surrogate)
CLB-d5	=	Chlorobenzene-d5	(An EPA 624 Surrogate)
BCP	=	2-Bromo-I-chloropropane	(An EPA 601 Surrogate)
TFT	=	a,a,a-Trifluorotoluene	(An EPA 602 Surrogate)
Decachlorobiphenyl	=	(an EPA 608/8080 Surrogate)	.

Definitions

- Surrogate Recovery = The recovery (expressed as a percent) of a non-method analyte (see surrogates listed above) added to the sample for the purpose of monitoring system performance.
- Matrix Spike Recovery = The recovery (expressed as a percent) of method analytes added to the sample for the purpose of determining any effect of sample composition on analyte recovery.
- Laboratory Replicate = Two sample aliquots taken in the analytical laboratory and analyzed separately with identical procedures. Analyses of laboratory duplicates give a measure of the preceision associated with laboratory procedures, but not with sample collection, preservation, or storage procedures.
- Field Duplicate = Two separate samples collected at the same time and place under identifical circumstances and treated exactly the same throughout field and laboratory procedures. Analysis of Field duplicates give a measure of the precision associated with sample collection, preservation and storage, as well as with laboratory procedures.
 - Relative Percent Difference (% RPD) = The precision measurement obtained on duplicate/replicate analyses. %RPD is calculated as:

%RPD = (value1 - value2) * 100% ave. value



CHAIN OF CUSTODY RECORD

Special Handling:

24 hour notification needed for rushes.

SPECTRUM	ANALYTICAL					Page	<u>. </u>	₀	f				24 hour notification needed for rushes. • Samples disposed of after 60 days unless otherwised instructed.											
Report To: _	Ecs Ba	44	Invoic	Invoice To: ECS Project No.: 40191 Site Name: Braffle Gos D. P. W. Well						llG	Telds	_												
Project Mgr.	: David Bal	"H		lo.:				RÇ	ν: _	27	Location: Route 30 State: V Sampler(s): L.GIUNDRE					ite: <u>VT</u>	_ _							
1=4℃ 2=H	Cl 3=H ₂ SO ₄ 4=HN	NO3 5=NaOH 6=	MeOH 7=_						Co	ntain	ers:					Anal	yses:					N	otes:	
DW=Drinkir SO=Soil S	r 	•			Vials	Glass	Jass	- · ·		80218 UTVESAN	1													
G=Grab C	E=Composite				 	Preservative		# Of VOA Vials	# Of Amber Glass	Of Clear Glass	Of Plastic		177	Wools										
Lab Id:	Sample Id:	Date:	Time:	Type	Matrix	Presei	Hd	JO#	/ JO #	# Of (I JO #			#2 <u>+</u>										
AB51541	Ecs-1	7/29/99	1:38	G	Gω	12	_	2	1				Χ̈́	Ø										
AB 5/542	TRIP	7/29/99	12:25	G	30	12		止	<u> </u>		<u> </u>		X							_				
AB				<u> </u>	<u>_</u> '						ļ								_					
AB	·						<u> </u>				<u> </u>								_	_				
AB .						<u> </u>	<u> </u>				ļ								_	_			···	
AB											<u> </u>								_	4		_		
AB												ļ							_					
AB						<u> </u>													_	_				
AB								<u> </u>				<u> </u>							\perp				<u>.</u>	
AB											ŀ													,
Additional Instructions: Rush Analysis					1	Re	linqui	ished	By:				$\overline{\Lambda}^{-}$	R	eceiv	ed B	y:]	Date:		Time:	
						5	wi	ife	~_			1)	Ja i	73	٠. ٠	<u> </u>	40			7/	30/	24	1510	
		A. A		/	·								/									\dashv		
Contracti	المامالية مسميانية	かハソト グル フンバル	02									1							- 1					



Massachusetts Certification M-MA 138 Connecticut Approva! # PH 0777 Rhode Island # 98 & Maine # n/a New Hampshire ID # 2538 New York ID #11393 Florida HR\$87448

ECS, Inc. 157 Old Guilford Road, #6 Brattleboro, VT 05301 August 9, 1999

Attn: David Balk

Client Project No.: 40191

Location: Brattleboro D.P.W. - VT

Lab ID No. Client ID Analysis Requested

AB51345 ECS-1 TPH by GC

Aromatic and Halogenated VOCs

Hanibal Tayeh
President/Laboratory Director

ENVIRONMENTAL ANALYSES

Laboratory Report

Client ID: ECS-1 Lab ID No: AB51345

Matrix: Soil Collected: 07/22/99 by ECS Received on 07/27/99 by KC QC and Data Review by MD

Location: Brattleboro D.P.W. - VT

Client Job No: 40191

Preservative: Refrigeration Container: 1 Amber Glass Condition of Sample as Received: Satisfactory Delivered by: Courier

Parameter	Result	MDL				
	1105011		Units	Method	Analyzed	Analyst
Benzene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW .
Toluene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW
Ethylbenzene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW _
m,p-Xylenes	Not detected	22.0	ug/L	SW846 8021B	08/01/99	GW
o-Xylerie	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW _
Naphthalene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW .
1,2,4-Trimethylbenzene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW
1,3,5-Trimethylbenzene	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW -
Methyl-t-butyl ether	Not detected	11.0	ug/L	SW846 8021B	08/01/99	GW
BFB Surrogate Recovery (%)	105		ug/L	SW846 8021B	08/01/99	GW _
% Solics	90.3	0.1	%	EPA 160.3	08/01/99	sms -

Laboratory Report

Client ID: ECS-1 Lab ID No.: AB51345 Location: Brattleboro D.P.W. - VT

Client Job No.: 40191

Matrix: Soil Collected: 07/22/99 by ECS Received on 07/27/99 by KC QC and Data Review by MD Preservative: Refrigeration Container: 1 Amber Glass

Condition of Sample as Received: Satisfactory Delivered by: Courier

Total Hydrocarbons by GC

Modified EPA Method 8100

Result (mg/Kg)	MDL	Extracted	Analyzed	Analyst
Not detected		08/02/99	08/02/99	LR
ton:				
Not detected	40	08/02/99	08/02/99	LR
Not detected	40	08/02/99	08/02/99	LR
Not detected	40	08/02/99	08/02/99	LR
Not detected	80	08/02/99	08/02/99	LR
Not detected	80	08/02/99	08/02/99	LR
Not detected	40	08/02/99	08/02/99	LR
Not detected	40	08/02/99	08/02/99	LR
Not detected	80	08/02/99	08/02/99	LR
Not detected		08/02/99	08/02/99	LR
90.3	0.1	08/01/99	08/01/99	SMS
	Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected Not detected	Not detected Not detected	Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 80 08/02/99 Not detected 80 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 40 08/02/99 Not detected 80 08/02/99 Not detected 40 08/02/99 Not detected 80 08/02/99 Not detected 80 08/02/99 Not detected 80 08/02/99	Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 40 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99 Not detected 80 08/02/99 08/02/99

Petroleum identification is determined by comparing the GC fingerprint obtained from the sample with a library of GC fingerprints obtained from petroleum products. Possible match categories are as follows;

Gasoline - includes regular, unleaded, premium, etc.

Fuel Oil #2 - includes home heating oil, #2 fuel oil and diesel.

Fuel Oil #4 - Includes #4 Fuel Oil.

Fuel Oil #6 - includes #6 oil and bunker "C" oil.

Motor Oil - includes virgin and waste automobile.

Ligroin - includes mineral spirits, petroleum naphtha, vm&p naphtha.

Aviation Fuels - includes Kerosene, Jet A and JP-4.

Other Oil - includes lubricating and cutting oil and silicon oil.

Factors such as microbial degradation, weathering and solubility generally prevent specific identification within a petroleum category. A finding of "unidentified" means that the sample fingerprint was characteristic of a petroleum product, but could not be matched to a fingerprint in the library.

After fingerprint identification, the amount present in the sample is quantified using a calibration curve prepared from a petroleum product of the same category as the identified petroleum. Unidentified petroleum is quantified using a petroleum calibration that approximates the distribution of compounds in the sample. A * in the results column indicates the petroleum calibration used to quantify unidentified samples.

Spectrum Analytical, Inc. Laboratory Report Supplement

References

Methods for the Determination of Organic Compounds in Drinking Water. EPA-600/4-88/039. EMSL 1988.

Methods for Chemical Analysis of Water and Wastes. EPA 600/4-79-020. EMSL 1983.

Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater. EPA 600/4-82-057. EMSL 1982.

Test Methods for Evaluating Solid Waste. Physical/Chemical Methods. EPA SW-846. 1986.

Standard Methods for the Examinatinon of Water and Wastes. APHA-AWWA-WPCF. 19th Edition. 1995.

Standard Methods for Comparison of Waterborne Petroleum Oils by Gas Chromatography. ASTM D 3328. 1982.

Oil Spill Identification System. U.S. Coast Guard CG-D-52-77, 1977.

Handbook for Analytical Quality Control in Water and Wastewater Laboratories, EPA 600/4-79-019, EMSL 1979.

Choosing Cost-Effective QA/QC (Quality Assurance/Quality Control) Programs for Chemical Analyses. EPA 600/4-85/056. EMSL 1985.

Report Notations

Not Detected,	=	The compound was not detected at a co	ncentration equal to or above
Not Det, ND or nd		the established method detection limit.	
NC	=	Not Calculated	
MCL	=	EPA Maximum Contamination Level	
VOA	==	Volatile Organic Analysis	
BFB	=	4-Bromofluorobenzene	(An EPA 624 Surrogate)
p-DFB	=	1,4-Difluorobenzene	(An EPA 624 Surrogate)
CLB-d5	=	Chlorobenzene-d5	(An EPA 624 Surrogate)
BCP	=	2-Bromo-1-chloropropane	(An EPA 601 Surrogate)
TFT	=	a,a,a-Trifluorotoluene	(An EPA 602 Surrogate)
Decachlorobiphenyl	=	(an EPA 608/8080 Surrogate)	

Definitions

Surrogate Recovery = The recovery (expressed as a percent) of a non-method analyte (see surrogates listed above) added to the sample for the purpose of monitoring system performance.

Matrix Spike Recovery = The recovery (expressed as a percent) of method analytes added to the sample for the purpose of determining any effect of sample composition on analyte recovery.

Laboratory Replicate = Two sample aliquots taken in the analytical laboratory and analyzed separately with identical procedures. Analyses of laboratory duplicates give a measure of the preceision associated with laboratory procedures, but not with sample collection, preservation, or storage procedures.

Field Duplicate = Two separate samples collected at the same time and place under identifical circumstances and treated exactly the same throughout field and laboratory procedures. Analysis of Field duplicates give a measure of the precision associated with sample collection, preservaton and storage, as well as with laboratory procedures.

Relative: Percent Difference (% RPD) = The precision measurement obtained on duplicate/replicate analyses. %RPD is calculated as:

%RPD = (value1 - value2) * 100% ave. value



CHAIN OF CUSTODY RECORD

Page _____ of ____

Special Handling:

■ Standard TAT - 7 to 10 business days

□ Rush TAT - Date Needed: ___

• All TATs subject to laboratory approval; min. 24 hour notification needed for rushes.

 Samples disposed of after 60 days unless otherwised instructed.

01 2011107.5																	onte	rwisea	msnuc	ica.			
Report To: _	ECS BRA	MLEBORO, V	Invoice	te To: FCS								Project No.: 40 191 Site Name: BLATTTEBORO D. P. W.											
												_[Location: Route 30, battleboro State: VT Sampler(s): Daylo Bala						17				
	<u>,</u>												Location: Touris State.						`				
Project Mgr.	DAUIDBI	464	P.O. No	o.: RQN: <u>2727</u>						Sampler(s): Day 18 Da 177													
1=4°C 2=H	Cl 3=H ₂ SO ₄ 4=HN	IO ₃ 5=NaOH 6=	=MeOH 7=_						Con	ntaine	ers:		Analyses:						Notes:				
DW=Drinking Water GW=Ground Water WW=Waste Water SO=Soil SL=Sludge O=Oil X1=X2=								/ials	Glass	lass			VOCS	HU1									
G=Grab C=Composite					хi	Preservative		# Of VOA Vials	# Of Amber Glass	Of Clear Glass	Of Plastic		812										
Lab Id:	Sample Id:	Date:	Time:	Type	_	Prese	hd			JO#	JO#		1208	810 M				_					
AB 51345	Ecs-1	7/22/99	12:00	6	50	1		<u> </u>	a				X	×			_ _		1	<u> </u>			
AB										<u> </u>								\perp					
AB								<u></u>															
AB																							
ΛВ																							
AB :																							
AB]													
AB							Ĭ																
AB.																							
AB																							
Additional	Instructions: VT	SCAN VO	C S			Re	linqu	ished	By:	0					ceive					Date	:	Т	ime:
					Met China							M	W	W	_			42	7/99	14:	00		
					/			ا	46	t/	_								2	127	7	160	
Fax resul	lts when available to (802) 257-	1603																				



Massachusetts Certification M-MA 138 Connecticut Approval # PH 0777 Rhode Island # 98 & Maine # n/a New Hampshire ID # 2538 New York ID #11393 Florida HR\$87448



ECS, Inc.

157 Old Guilford Road, #6 Brattleboro, VT 05301

Attn: David Balk

Client Project No.: 40191

Location: DPW/Rt 30 - Brattleboro, VT

September 24, 1999

Lab ID No.	Client ID	Analysis Requested
AB56336	SB-1	EPA Method 8021B TPH by GC
AB56337	SB-2	EPA Method 8021B TPH by GC
AB56338	SB-3	EPA Method 8021B TPH by GC
AB56339	DÜP	EPA Method 8021B
AB56340	TRIP	EPA Method 8021B

Hanibal Tayoh Presideht/Laboratory Director

Laboratory Report

Client ID: SB-1

Lab ID No: AB56336

Location: DPW/Rt 30 - Brattleboro, VT Client Job No: 40191

Matrix: Ground Water Sampled on09/09/99 Client ECS Received on 09/09/99 by KC QC and Data Review by DDR

Preservative: Refrigeration, HCl Container: 2 VOA Vials Condition of Sample as Received: Satisfactory Delivered by: Courier

Volatile Organics

Parameter for AB56336	Result (in ug/L)	MDL	Analyzed	Analyst
Benzene	Not detected	1.0	09/21/99	GW
Toluene	Not detected	1.0	09/21/99	GW
Ethylbenzene	Not detected	1.0	09/21/99	GW
m,p-Xylenes	Not detected	2.0	09/21/99	GW
o-Xylene	Not detected	1.0	09/21/99	GW
Naphthalene	Not detected	1.0	09/21/99	GW
1,2,4-Trimethylbenzene	Not detected	1.0	09/21/99	GW
1,3,5-Trimethylbenzene	Not detected	1.0	09/21/99	GW
Methyl-t-butyl ether	Not detected	1.0	09/21/99	GW
Bromofluorobenzene (%SR)	96		09/21/99	GW

Laboratory Report

Client ID: SB-1 Lab ID No.: AB56336

Matrix: Ground Water Collected: 09/09/99 by ECS Received on 09/09/99 by KC QC and Data Review by DDR

Location: DPW/Rt 30 - Brattleboro, VT

Client Job No.: 40191

Preservative: Refrigeration Container: 1 Amber Glass

Condition of Sample as Received: Satisfactory Delivered by: Courier

Total Hydrocarbons by GC

Modified EPA Method 8100

Parameter	Result (mg/L)	MDL	Extracted	Analyzad	A = almat
Total Hydrocarbons (GC)	Not detected		09/15/99	Analyzed 09/17/99	Analyst LR
Fingerprint based quantification	ion:				,
Gasoline	Not detected	0.2	09/15/99	09/17/99	LR
Fuel Oil #2	Not detected	0.4	09/15/99	09/17/99	LR
Fuel Oil #4	Not detected	0.7	09/15/99	09/17/99	LR
Fuel Oil #6	Not detected	0.7	09/15/99	09/17/99	LR
Motor Oil	Not detected	0.7	09/15/99	09/17/99	LR
Ligroin	Not detected	0.4	09/15/99	09/17/99	LR
Aviation Fuel	Not detected	0.4	09/15/99	09/17/99	LR
Other Oil	Not detected	0.7	09/15/99	09/17/99	LR
Unidentified	Not detected		09/15/99	09/17/99	LR ·

Petroleum identification is determined by comparing the GC fingerprint obtained from the sample with a library of GC fingerprints obtained from petroleum products. Possible match categories are as follows;

Gasoline - includes regular, unleaded, premium, etc.

Fuel Oil #2 - includes home heating oil, #2 fuel oil and diesel.

Fuel Oil #4 - Includes #4 Fuel Oil.

Fuel Oil #6 - includes #6 oil and bunker "C" oil.

Motor Oil - includes virgin and waste automobile.

Ligroin - includes mineral spirits, petroleum naphtha, vm&p naphtha.

Aviation Fuels - includes Kerosene, Jet A and JP-4.

Other Oil - includes lubricating and cutting oil and silicon oil.

Factors such as microbial degradation, weathering and solubility generally prevent specific identification within a petroleum category. A finding of "unidentified" means that the sample fingerprint was characteristic of a petroleum product, but could not be matched to a fingerprint in the library.

After fingerprint identification, the amount present in the sample is quantified using a calibration curve prepared from a petroleum product of the same category as the identified petroleum. Unidentified petroleum is quantified using a petroleum calibration that approximates the distribution of compounds in the sample. A * in the results column indicates the petroleum calibration used to quantify unidentified samples.

Laboratory Report

Client ID: SB-2

Lab ID No: AB56337

Location: DPW/Rt 30 - Brattleboro, VT

Client Job No: 40191

Matrix: Ground Water Sampled on09/09/99 Client ECS Received on 09/09/99 by KC QC and Data Review by MD

Preservative: Refrigeration, HCl Container: 2 VOA Vials Condition of Sample as Received: Satisfactory Delivered by: Courier

Volatile Organics

_	Parameter for AB56337	Result (in ug/L)	MDL	Analyzed	Analyst
	Benzene	Not detected	1.0	09/21/99	GW
_	Toluene	Not detected	1.0	09/21/99	GW
	Ethylbenzene	Not detected	1.0	09/21/99	GW
	m,p-Xylenes	Not detected	2.0	09/21/99	GW
	o-Xylene	Not detected	1.0	09/21/99	GW
	Naphthalene	Not detected	1.0	09/21/99	GW
	1,2,4-Trimethylbenzene	Not detected	1.0	09/21/99	GW
_	1,3,5-Trimethylbenzene	Not detected	1.0	09/21/99	GW
	Methyl-t-butyl ether	Not detected	1.0	09/21/99	GW
-	- a 1 (MOD)	0.1		09/21/99	GW
	Bromofluorobenzene (%SR)	91		64/21/49	OW.

Laboratory Report

Client ID: SB-2

Lab ID No.: AB56337

Location: DPW/Rt 30 - Brattleboro, VT

Client Job No.: 40191

Matrix: Ground Water Collected: 09/09/99 by ECS Received on 09/09/99 by KC QC and Data Review by MD

Preservative: Refrigeration Container: 1 Amber Glass

Condition of Sample as Received: Satisfactory Delivered by: Courier

Total Hydrocarbons by GC

Modified EPA Method 8100

Parameter	Result (mg/L)	MDL	Extracted	Analyzed	Analyst
Total Hydrocarbons (GC)	Not detected		09/15/99	09/17/99	MB
Fingerprint based quantificati	ion:				
Gasoline	Not detected	0.2	09/15/99	09/17/99	MB
Fuel Oil #2	Not detected	0.4	09/15/99	09/17/99	MB
Fuel Oil #4	Not detected	0.7	09/15/99	09/17/99	MB
Fuel Oil #6	Not detected	0.7	09/15/99	09/17/99	MB
Motor Oil	Not detected	0.7	09/15/99	09/17/99	MB
Ligroin	Not detected	0.4	09/15/99	09/17/99	MB
Aviation Fuel	Not detected	0.4	09/15/99	09/17/99	MB
Other Oil	Not detected	0.7	09/15/99	09/17/99	MB
Unidentified	Not detected		09/15/99	09/17/99	MB

Petroleum identification is determined by comparing the GC fingerprint obtained from the sample with a library of GC fingerprints obtained from petroleum products. Possible match categories are as follows;

Gasoline - includes regular, unleaded, premium, etc.

Fuel Oil #2 - includes home heating oil, #2 fuel oil and diesel.

Fuel Oil #4 - Includes #4 Fuel Oil.

Fuel Oil #6 - includes #6 oil and bunker "C" oil.

Motor Oil - includes virgin and waste automobile.

Ligroin - includes mineral spirits, petroleum naphtha, vm&p naphtha.

Aviation Fuels - includes Kerosene, Jet A and JP-4.

Other Oil - includes lubricating and cutting oil and silicon oil.

Factors such as microbial degradation, weathering and solubility generally prevent specific identification within a petroleum category. A finding of "unidentified" means that the sample fingerprint was characteristic of a petroleum product, but could not be matched to a fingerprint in the library.

After fingerprint identification, the amount present in the sample is quantified using a calibration curve prepared from a petroleum product of the same category as the identified petroleum. Unidentified petroleum is quantified using a petroleum calibration that approximates the distribution of compounds in the sample. A * in the results column indicates the petroleum calibration used to quantify unidentified samples.

Laboratory Report

Client ID: SB-3

Lab ID No: AB56338

Location: DPW/Rt 30 - Brattleboro, VT

Client Job No: 40191

Matrix: Ground Water Sampled on09/09/99 Client ECS Received on 09/09/99 by KC QC and Data Review by DDR

Preservative: Refrigeration, HCl Container: 2 VOA Vials Condition of Sample as Received: Satisfactory Delivered by: Courier

Volatile Organics

Parameter for AB56338	Result (in ug/L)	MDL			
i di dineter for 1 2550550	2000020 (9-)		Analyzed	Analyst	
Benzene	Not detected	1.0	09/21/99	GW	
Toluene	Not detected	1.0	09/21/99	GW	
Ethylbenzene	Not detected	1.0	09/21/99	GW	
m,p-Xylenes	Not detected	2.0	09/21/99	GW	
o-Xylene	Not detected	1.0	09/21/99	GW	
Naphthalene	Not detected	1.0	09/21/99	GW	
1,2,4-Trimethylbenzene	Not detected	1.0	09/21/99	GW	
1,3,5-Trimethylbenzene	Not detected	1.0	09/21/99	GW	
Methyl-t-butyl ether	Not detected	1.0	09/21/99	GW	
Bromofluorobenzene (%SR)	91		09/21/99	GW	

Laboratory Report

Client ID: SB-3

Lab ID No.: AB56338

Location: DPW/Rt 30 - Brattleboro, VT

Client Job No.: 40191

Matrix: Ground Water Collected: 09/09/99 by ECS Received on 09/09/99 by KC QC and Data Review by DDR

Preservative: Refrigeration Container: 1 Amber Glass

Condition of Sample as Received: Satisfactory Delivered by: Courier

Total Hydrocarbons by GC

Modified EPA Method 8100

Parameter	Result (mg/L)	Result (mg/L) MDL Not detected		Analyzed	Analyst
Total Hydrocarbons (GC)	Not detected			09/17/99	MB
Fingerprint based quantificati	ion:				
Gasoline	Not detected	0.2	09/15/99	09/17/99	MB -
Fuel Oil #2	Not detected	0.4	09/15/99	09/17/99	MB
Fuel Oil #4	Not detected	0.7	09/15/99	09/17/99	MB
Fuel Oil #6	Not detected	0.7	09/15/99	09/17/99	MB
Motor Oil	Not detected	0.7	09/15/99	09/17/99	MB
Ligroin	Not detected	0.4	09/15/99	09/17/99	MB
Aviation Fuel	Not detected	0.4	09/15/99	09/17/99	MB
Other Oil	Not detected	0.7	09/15/99	09/17/99	MB
Unidentified	Not detected		09/15/99	09/17/99	MB ·

Petroleum identification is determined by comparing the GC fingerprint obtained from the sample with a library of GC fingerprints obtained from petroleum products. Possible match categories are as follows;

Gasoline - includes regular, unleaded, premium, etc.

Fuel Oil #2 - includes home heating oil, #2 fuel oil and diesel.

Fuel Oil #4 - Includes #4 Fuel Oil.

Fuel Oil #6 - includes #6 oil and bunker "C" oil.

Motor Oil - includes virgin and waste automobile.

Ligroin - includes mineral spirits, petroleum naphtha, vm&p naphtha.

Aviation Fuels - includes Kerosene, Jet A and JP-4.

Other Oil - includes lubricating and cutting oil and silicon oil.

Factors such as microbial degradation, weathering and solubility generally prevent specific identification within a petroleum category. A finding of "unidentified" means that the sample fingerprint was characteristic of a petroleum product, but could not be matched to a fingerprint in the library.

After fingerprint identification, the amount present in the sample is quantified using a calibration curve prepared from a petroleum product of the same category as the identified petroleum. Unidentified petroleum is quantified using a petroleum calibration that approximates the distribution of compounds in the sample. A * in the results column indicates the petroleum calibration used to quantify unidentified samples.

Laboratory Report

Client ID: DUP

Lab ID No: AB56339

Location: DPW/Rt 30 - Brattleboro, VT Client Job No: 40191

Matrix: Ground Water Sampled on09/09/99 Client ECS Received on 09/09/99 by KC QC and Data Review by MD

Preservative: Refrigeration, HCl Container: 2 VOA Vials Condition of Sample as Received: Satisfactory Delivered by: Courier

Volatile Organics

_	Parameter for AB56339	Result (in ug/L)	MDL	.	414
	Benzene	Not detected	2.0	Analyzed 09/09/99	Analyst SK
_	Toluene	Not detected	2.0	09/09/99	SK
	Ethylbenzene	Not detected	2.0	09/09/99	SK
	m,p-Xylenes	Not detected	4.0	09/09/99	SK
_	o-Xylene	Not detected	2.0	09/09/99	SK
	Naphthalene	Not detected	2.0	09/09/99	SK
	1,2,4-Trimethylbenzene	Not detected	2.0	09/09/99	SK
_	1,3,5-Trimethylbenzene	Not detected	2.0	09/09/99	SK
	Methyl-t-butyl ether	Not detected	2.0	09/09/99	SK
_	Bromofluorobenzene (%SR)	101	0.00	09/09/99	SK

Laboratory Report

Client ID: TRIP

Lab ID No: AB56340

Location: DPW/Rt 30 - Brattleboro, VT Client Job No: 40191

Matrix: Deionized Water Sampled on09/09/99 Client ECS Received on 09/09/99 by KC QC and Data Review by MD

Preservative: Refrigeration, HCl Container: 1 VOA Vial Condition of Sample as Received: Satisfactory Delivered by: Courier

Volatile Organics

Parameter for AB56340	Result (in ug/L)	MDL		•	
	,		Analyzed	Analyst	
Benzene	Not detected	1 .0	09/21/99	SK -	
Toluene	Not detected	1.0	09/21/99	SK	
Ethylbenzene	Not detected	1.0	09/21/99	SK	
m,p-Xylenes	Not detected	2.0	09/21/99	SK	
o-Xylene	Not detected	1.0	09/21/99	SK	
Naphthalene	Not detected	1.0	09/21/99	SK	
1,2,4-Trimethylbenzene	Not detected	1.0	09/21/99	SK	
1,3,5-Trimethylbenzene	Not detected	1.0	09/21/99	SK	
Methyl-t-butyl ether	Not detected	1.0	09/21/99	sk -	
Bromofluorobenzene (%SR)	86		09/21/99	sĸ	

Spectrum Analytical, Inc. / Laboratory Report Supplement

References

Methods for the Determination of Organic Compounds in Drinking Water. EPA-600/4-88/039. EMSL 1988.

Methods for Chemical Analysis of Water and Wastes. EPA 600/4-79-020. EMSL 1983.

Methods for Organic Chemical Analysis of Municipal and Industrial Wastewater. EPA 600/4-82-057. EMSL 1982.

Test Methods for Evaluating Solid Waste. Physical/Chemical Methods. EPA SW-846. 1986.

Standard Methods for the Examination of Water and Wastes. APHA-AWWA-WPCF. 19th Edition. 1995.

Standard Methods for Comparison of Waterborne Petroleum Oils by Gas Chromatography. ASTM D 3328. 1982.

Oil Spill Identification System. U.S. Coast Guard CG-D-52-77. 1977.

Handbook for Analytical Quality Control in Water and Wastewater Laboratories. EPA 600/4-79-019. EMSL 1979.

Choosing Cost-Effective QA/QC (Quality Assurance/Quality Control) Programs for Chemical Analyses. EPA 600/4-85/056. EMSL 1985.

Report Notations

Not Detected, Not Det, ND or nd	=	The compound was not detected at a concentration equal to or above the established method detection limit.								
NC	=	Not Calculated								
MCL	=	EPA Maximum Contamination Level								
VOA	=	Volatile Organic Analysis								
BFB	=	4-Bromofluorobenzene	(An EPA 624 Surrogate)							
p-DFB	=	1,4-Difluorobenzene	(An EPA 624 Surrogate)							
CLB-d5	_ =	Chlorobenzene-d5	(An EPA 624 Surrogate)							
BCP	=	2-Bromo-1-chloropropane	(An EPA 601 Surrogate)							
TFT	==	a,a,a-Trifluorotoluene	(An EPA 602 Surrogate)							
Decachlorobiphenyl	=	(an EPA 608/8080 Surrogate)								

Definitions

Surrogate Recovery = The recovery (expressed as a percent) of a non-method analyte (see surrogates listed above) added to the sample for the purpose of monitoring system performance.

Matrix Spike Recovery = The recovery (expressed as a percent) of method analytes added to the sample for the purpose of determining any effect of sample composition on analyte recovery.

Laboratory Replicate = Two sample aliquots taken in the analytical laboratory and analyzed separately with identical procedures. Analyses of laboratory duplicates give a measure of the precision associated with laboratory procedures, but not with sample collection, preservation, or storage procedures.

Field Duplicate = Two separate samples collected at the same time and place under identical circumstances and treated exactly the same throughout field and laboratory procedures. Analysis of Field duplicates give a measure of the precision associated with sample collection, preservation and storage, as well as with laboratory procedures.

Relative Percent Difference (% RPD) = The precision measurement obtained on duplicate/replicate analyses. %RPD is calculated as:

%RPD = (value1 - value2) * 100% ave. value



CHAIN OF CUSTODY RECORD Special Handling: Special Handling: Special Handling: Standard TAT - 7 to 10 business days

Special Handling:

· All TATs subject to laboratory approval; min. 24 hour notification needed for rushes.

SPECTRUM	ANALYTICAL					Page	• Samples dis otherwised						sposed of after 60 days unless instructed.										
Report To: ECS-VT Invoice						nvoice To: ES Agawam								Project No.: 4019 Site Name: 6 22 4 1000 DPW									
Project Mgr.: D. Ball P.O. No				P.O. No.: RQN: 							_ i	Location Rt. 30 Bratt. State: VT Sampler(s): L.Gi MME								/ <u>]</u>			
1=4°C 2=HCl 3=H ₂ SO ₄ 4=HNO ₃ 5=NaOH 6=MeOH 7=_			=MeOH 7=_						Containers:			İ_	Analyses:						Notes:				
DW=Drinkin SO=Soil SI	g Water GW=Grou L=Sludge O=Oil 3	and Water WW: X1= DH2 O	=Waste Water X2=		·			Vials	Glass	lass		•	Σ	N N									
G=Grab C	=Composite	1			ı X.	Preservative		VOA	# Of Amber Glass	Of Clear Glass	Of Plastic	d	200	194									
Lab Id:	Sample Id:	Date:	Time:	Type	Matrix		Hd	JO#	JO#	#Of	#Of		12	8071									
AB 56336	<u> 56-1</u>	919199	10:00	6	GW	1			1				1										
AB \$4.337	SB2		10:20	4)	GU				ı				ſ.			ļ		•					
AB <i>56338</i>	SB-3		11:00	S	Gil	1			,				1										
AB 56-336	SB-1		10:00	5	21	1,2		2						1									
AB 56337	SB-2		10:20	6	SIL	1,2		2						1									
AB 57338	SB-3		11:00	6	11			2						1									
AB 56339	DUP	1/		(4)	1		,	7						1.			1						
AB 52340	TRIP	V	8:00	6	X.	1.2		1						1			\top						
AB					•	Ì								1		1.				1	i		
AB															\top								
Additional Instructions: LAPY COLC			Relinquished By:						Received By: Date: Time							me:							
_VTV	OCSCAN]	_	1	1		Ø,	m	17			13	VA O	mi	16	nl	hu	人	9	1919	9]/:	30
		.		L	7m	9111	11	77/	- Vi		0		<u>شعب</u>	1	, I>	L			9	19/0	79	110	SPA
Fax results	when available to (🖔	02 257.	-1195	<u>'</u>	- 6 10	-40 <u>~</u>	-		L ~~		25.7		×	- / \	"				7	7/	1	 7 -	~